

## Sensor Type 10. 3,000 ohm Thermistor Celsius

Temp	Resis	Temp	Resis	Temp	Resis	Temp	Resis
-40	100618	8	6577	56	863	104	181
-39	94180	9	6266	57	832	105	176
-38	88193	10	5971	58	802	106	171
-37	82624	11	5692	59	774	107	167
-36	77442	12	5428	60	746	108	162
-35	72615	13	5177	61	720	109	157
-34	68122	14	4940	62	695	110	153
-33	63932	15	4714	63	670	111	149
-32	60025	16	4500	64	647	112	145
-31	56382	17	4297	65	625	113	141
-30	52982	18	4105	66	603	114	137
-29	49808	19	3922	67	583	115	133
-28	46843	20	3748	68	563	116	130
-27	44073	21	3583	69	544	117	126
-26	41784	22	3426	70	525	118	123
-25	39062	23	3277	71	508	119	120
-24	36796	24	3135	72	491	120	117
-23	34675	25	3000	73	475	121	114
-22	32690	26	2872	74	459	122	111
-21	30830	27	2749	75	444	123	108
-20	29087	28	2633	76	430	124	105
-19	27453	29	2522	77	416	125	102
-18	25921	30	2417	78	402	126	100
-17	24483	31	2316	79	389	127	97
-16	23134	32	2220	80	377	128	95
-15	21866	33	2129	81	365	129	92
-14	20680	34	2042	82	353	130	90
-13	19558	35	1959	83	342	131	88
-12	18507	36	1880	84	332	132	86
-11	17518	37	1804	85	321	133	83
-10	16589	38	1732	86	311	134	81
-9	15713	39	1663	87	302	135	79
-8	14889	40	1597	88	292	136	78
-7	14114	41	1535	89	283	137	76
-6	13383	42	1475	90	275	138	74
-5	12694	43	1417	91	267	139	72
-4	12045	44	1362	92	259	140	70
-3	11433	45	1310	93	251	141	69
-2	10855	46	1260	94	243	142	67
-1	10310	47	1212	95	236	143	65
0	9795	48	1166	96	229	144	64
1	9309	49	1122	97	222	145	62
2	8850	50	1080	98	216	146	61
3	8416	51	1040	99	210	147	60
4	8006	52	1002	100	204	148	58
5	7619	53	965	101	198	149	57
6	7252	54	929	102	192	150	56
7	6905	55	895	103	187		